



Effect of Adventitious Carbon on the Environmental Degradation of SiC/BN/SiC Composites

L.U.J.T. Ogbuji
QSS Group, Inc., Cleveland, Ohio

H.M. Yun
Cleveland State University, Cleveland, Ohio

J. DiCarlo
Glenn Research Center, Cleveland, Ohio

The NASA STI Program Office . . . in Profile

Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA Scientific and Technical Information (STI) Program Office plays a key part in helping NASA maintain this important role.

The NASA STI Program Office is operated by Langley Research Center, the Lead Center for NASA's scientific and technical information. The NASA STI Program Office provides access to the NASA STI Database, the largest collection of aeronautical and space science STI in the world. The Program Office is also NASA's institutional mechanism for disseminating the results of its research and development activities. These results are published by NASA in the NASA STI Report Series, which includes the following report types:

- **TECHNICAL PUBLICATION.** Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA's counterpart of peer-reviewed formal professional papers but has less stringent limitations on manuscript length and extent of graphic presentations.
- **TECHNICAL MEMORANDUM.** Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.
- **CONTRACTOR REPORT.** Scientific and technical findings by NASA-sponsored contractors and grantees.
- **CONFERENCE PUBLICATION.** Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or cosponsored by NASA.
- **SPECIAL PUBLICATION.** Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.
- **TECHNICAL TRANSLATION.** English-language translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services that complement the STI Program Office's diverse offerings include creating custom thesauri, building customized data bases, organizing and publishing research results . . . even providing videos.

For more information about the NASA STI Program Office, see the following:

- Access the NASA STI Program Home Page at <http://www.sti.nasa.gov>
- E-mail your question via the Internet to help@sti.nasa.gov
- Fax your question to the NASA Access Help Desk at 301-621-0134
- Telephone the NASA Access Help Desk at 301-621-0390
- Write to:
NASA Access Help Desk
NASA Center for AeroSpace Information
7121 Standard Drive
Hanover, MD 21076



Effect of Adventitious Carbon on the Environmental Degradation of SiC/BN/SiC Composites

L.U.J.T. Ogbuji
QSS Group, Inc., Cleveland, Ohio

H.M. Yun
Cleveland State University, Cleveland, Ohio

J. DiCarlo
Glenn Research Center, Cleveland, Ohio

Prepared for the
Seventh Conference on Interphase Phenomena in Composite Materials
sponsored by the Interphase Phenomena in Composite Materials
Arcachon, France, September 9–14, 2001

National Aeronautics and
Space Administration

Glenn Research Center

Trade names or manufacturers' names are used in this report for identification only. This usage does not constitute an official endorsement, either expressed or implied, by the National Aeronautics and Space Administration.

Available from

NASA Center for Aerospace Information
7121 Standard Drive
Hanover, MD 21076

National Technical Information Service
5285 Port Royal Road
Springfield, VA 22100

Available electronically at <http://gltrs.grc.nasa.gov/GLTRS>

Effect of Adventitious Carbon on the Environmental Degradation of SiC/BN/SiC Composites

L.U.J.T. Ogbuji

QSS Group

Cleveland, Ohio

H.M. Yun

Cleveland State University

Cleveland, Ohio

J. DiCarlo

National Aeronautics and Space Administration

Glenn Research Center

Cleveland, Ohio 44135

Abstract

Pesting remains a major obstacle to the application of SiC/SiC composites in engine service, and selective degradation of the boron nitride interphase at intermediate temperatures is of primary concern. However, significant progress has been made on interphase improvement recently, and we now know more about the phenomenon and ways to suppress it. By screening SiC/BN/SiC materials through characterization of strength and microstructures after exposure in a burner rig, some factors that control pesting in these composites have been determined. A key precaution is careful control of elemental carbon presence in the interphase region.

Introduction

SiC/SiC composites are strong contenders for high-temperature application in engine hot sections, where oxidative degradation by aggressive ambient gases makes the durability of components an important issue. In such environment the interphase (the material at the fiber-matrix interface) is key to composite behavior and component life. The interphase is designed as the weak mechanical link in a composite, to ensure debonding between fiber and matrix and deflection of cracks originating in the matrix. Unfortunately, it is also the weakest link in terms of environmental effects because the most mechanically effective interphase materials, carbon and boron nitride, are also prone to easy oxidation. Several studies in our laboratory and elsewhere have demonstrated that the highly deleterious phenomenon of pest degradation or *pesting* in SiC/SiC composites arises from selective environment attack of the interphase [1-4]. Damage from pesting ranges from generation of localized fiber flaws to embrittlement of the composite as the compliant interphase is replaced by rigid silica, which fuses the components together.

Because carbon leaves no solid residue on oxidation, it is no longer seriously considered a suitable interphase for SiC/SiC composites, and the state-of-the-art interphase in these systems is pyrolytic boron nitride. Yet *py*-BN oxidizes almost as easily as *py*-C, and the resulting oxide forms a low-melting eutectic with silica. Studies conducted from ~600 to 1000°C in a burner rig, to simulate an engine environment at intermediate temperatures, have shown that chain reactions easily set in at the fiber-matrix interface: B₂O₃ from the interphase BN dissolves the fiber and/or matrix to form a borosilicate (which may stay liquid at temperatures as low as 372°C); ambient moisture hydrolyzes the borosilicate, eventually leaving SiO₂ which bonds the fiber and matrix together.

Because carbon is a common denominator of most precursors and reaction products in the processing of SiC-based composites, it is important to understand the role it plays in the environmental degradation of these materials.

Materials and Procedure

Of the SiC/BN/SiC varieties reported in the literature only two have reached a sufficient state of development to attract serious attention for commercial or aerospace applications. Both varieties feature a matrix of melt-infiltration silicon carbide (*mi*-SiC) and chemical-vapor-infiltration boron nitride (*cvi*-BN) as the interphase. They differ in the reinforcing fibers, one utilizing the Hi-NicalonTM or Hi-Nicalon(S)TM fibers made by Nippon Carbon Company, and the other Dow Corning's SylramicTM fibers. Both Hi-Nicalon/BN/SiC and Sylramic/BN/SiC composites were investigated in this study under the NASA's Enabling Propulsion Materials (EPM) and Ultra-Efficient Engine Technology (UEET) programs for advanced aerospace materials. They were assessed for pest resistance.

An outline of the procedure is shown in Fig. 1; details appear elsewhere [1]. Panels of the composite manufactured by Honeywell Advanced Composites Inc. (HACI), cut to expose fiber and interphase ends, were held for 100 hours in a burner rig at atmospheric pressure. The 0.3-Mach flame of the burner rig was struck by the combustion of Jet-A fuel in air and contains 10% H₂O among the combustion products. After burner rig exposure the samples were broken in tension, and characterized by Scanning Electron Microscopy (SEM) and Auger Electron Spectrometry (AES) on surfaces exposed by breaking thin slivers of the sample inside the AES spectrometer, to prevent contamination by carbon in the ambient; SEM was also performed on fracture surfaces exposed by the tensile test, and on polished surfaces. For characterization of the as-received material the SEM and AES samples were taken from the grip ends of the tensile bars (Fig. 1).




Fig. 1 (A).—Picture of burner rig exposure, and (B) schematics showing SEM and AES examination locations; sample temperatures while in the burner rig are indicated

Results and Discussion

While purity and crystallinity, as well as Si-doping, are now known to improve oxidation resistance of the BN interphase, the most significant factor in SiC/BN/SiC pesting is the occurrence of free carbon under the BN layer. In this regard, it was found that Sylramic-fiber-reinforced composites type may be further split into two categories, depending on whether polyethylene oxide (PEO) or polyvinyl alcohol (PVA) sizing was used to protect the fibers before and during composite processing. Sylramic(PVA)/BN/SiC composites showed no evidence of pesting during the 100-hour exposure in the burner rig, while the Sylramic(PEO)/BN/SiC variety pested severely. In contrast, all Hi-Nicalon/BN/SiC materials pested severely, regardless of whether the fiber was the regular Hi-NicalonTM or Hi-Nicalon(S)TM variety. Table 1 summarizes these findings.

Sample	HN1	001	052	166	009	033	011
$\Delta\sigma$ in APBR ¹	-61%	-56%	-41%	-58%	-27%	0	0
$\Delta\epsilon$ in APBR ¹	-90%	-78%	-80%	-75%	-28%	0	0
Fiber type	H-N ²	HN-S ³	HN-S ³	Syl ⁴	Syl ⁴	Syl ⁴	Syl ⁴
Sizing type	PVA	PVA	PVA	PEO	PVA	PVA	PVA
Carbon Under BN?	yes	yes	yes	yes	no	no	no

Table 1.—Categories of SiC/BN/SiC composite determined from pest assessment

(¹From tensile test; ² Hi-NicalonTM; ³Hi-Nicalon(S)TM; ⁴SylramicTM)

The materials that exhibited severe pesting were characterized by one common feature: the presence of a continuous layer of carbon between the BN interphase and the SiC fiber. In Hi-Nicalon/BN/SiC composites the carbon was in the form of a compact film, while in the Sylramic(PEO)/BN/SiC varieties it was a skeletal network. Pesting was promoted by oxidative removal of this carbon layer, leaving the broad flank of the BN layer exposed to attack by flame oxidants. In the materials containing Hi-Nicalon-type fibers the layers of carbon came from the stoichiometric excess in the fiber; in composites made with PEO-sized Sylramic fibers, the carbon was a skeletal residue from the sizing.

Note in Fig. 1 that the flame impinged on the ends of the [0°] fibers in the horizontal tows; hence, degradation must start in these fibers. Yet pesting was determined from fracture of the [90°] fibers along the sample length. Thus, degradation spread from the [0°] to the [90°] fibers, which implies that the interphase and its associated carbon sub-layer are in contact within and between tows. That was also evident on polished sections of the samples, which showed that fiber-to-fiber contact (via the BN coating) is the rule. Clearly, contact between the BN coatings around adjacent fibers is a pre-disposing factor (without which the mere presence of a carbon layer might not cause pesting), particularly when the contact is extended to other dimensions through the splicing of tows.




Fig. 2.—SEM showing a fold of carbon around the BN interphase (magnified in inset) in a Hi-Nicalon(S)/BN/SiC composite. This material pested severely in the burner rig.

Summary and Conclusion

By exposing SiC/BN/SiC composites in the burner rig and examining them for residual strength and microstructure, it has been determined that severe pest degradation of these composites by a jet flame is associated with the presence of graphitic carbon beneath the BN. Whether it originates from excess carbon in the fiber or from desizing char yield, the carbon network undermines the interphase since its removal by oxidation creates a route for deep penetration of the composite by the ambient gases. Consequently, one important precaution in SiC/BN/SiC processing is to ensure the strict absence of elemental carbon in the interphase region.

References

1. L.U.J.T. Ogbuji, "A Pervasive Mode of Oxidative Degradation in a SiC-SiC Composite", *J. Am. Ceram. Soc.*, 81 [11] 2777-84 (1998)

2. F.E. Heredia, J.C. McNulty, F.W. Zok, and A.G. Evans, "Oxidation Embrittlement Probe for Ceramic-Matrix Composites", *J. Am. Ceram. Soc.*, **78** [8] 2097-100 (1995)
3. J. DiCarlo, H.M. Yun, G.N. Morscher, and L.U.J.T. Ogbuji, "Progress in SiC/SiC Composites for Engine Applications" (to appear in Proceedings of Materials Week 2001, Munich Germany)
4. G.N. Morscher, D.R. Bryant, and R.E. Tressler, "Environmental Durability of BN-Based Interphases (for SiC/SiC Composites) in H₂O-Containing Atmospheres at Intermediate Temperatures", Ceramic Engineering & Science Proceedings Vol. 18, Issue 3 (1997) 525-33

REPORT DOCUMENTATION PAGE			<i>Form Approved OMB No. 0704-0188</i>
<p>Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.</p>			
1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE	3. REPORT TYPE AND DATES COVERED	
	April 2002	Technical Memorandum	
4. TITLE AND SUBTITLE		5. FUNDING NUMBERS	
Effect of Adventitious Carbon on the Environmental Degradation of SiC/BN/SiC Composites		WU-714-04-13-00	
6. AUTHOR(S)		7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)	
L.U.J.T. Ogbuji, H.M. Yun, and J. DiCarlo		National Aeronautics and Space Administration John H. Glenn Research Center at Lewis Field Cleveland, Ohio 44135-3191	
8. PERFORMING ORGANIZATION REPORT NUMBER		9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)	
E-13262		National Aeronautics and Space Administration Washington, DC 20546-0001	
10. SPONSORING/MONITORING AGENCY REPORT NUMBER		11. SUPPLEMENTARY NOTES	
NASA TM—2002-211494		<p>Prepared for the Seventh Conference on Interphase Phenomena in Composite Materials sponsored by the Interphase Phenomena in Composite Materials, Arcachon, France, September 9–14, 2001. L.U.J.T. Ogbuji, QSS Group, Inc., Cleveland, Ohio; H.M. Yun, Cleveland State University, Cleveland, Ohio; and J. DiCarlo, NASA Glenn Research Center. Responsible person, L.U.J.T. Ogbuji, organization code 5160, 216-433-6463.</p>	
12a. DISTRIBUTION/AVAILABILITY STATEMENT		12b. DISTRIBUTION CODE	
Unclassified - Unlimited Subject Category: 10		Distribution: Nonstandard	
Available electronically at http://gltrs.grc.nasa.gov/GLTRS			
This publication is available from the NASA Center for AeroSpace Information, 301-621-0390.			
13. ABSTRACT (Maximum 200 words)			
<p>Pesting remains a major obstacle to the application of SiC/SiC composites in engine service and selective degradation of the boron nitride interphase at intermediate temperatures is of primary concern. However, significant progress has been made on interphase improvement recently and we now know more about the phenomenon and ways to suppress it. By screening SiC/BN/SiC materials through characterization of strength and microstructures after exposure in a burner rig, some factors that control pesting in these composites have been determined. A key precaution is careful control of elemental carbon presence in the interphase region.</p>			
14. SUBJECT TERMS			15. NUMBER OF PAGES
SiC/SiC composites; Pest prevention and control; Elemental carbon			11
			16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT
Unclassified	Unclassified	Unclassified	